


MAXTOP VENTURE

TOYOTA HILUX DOUBLE CAB 2018+ A-DECK


OWNER'S MANUAL

Operation




Adjustment



Adjustment





Safety Secure





Safety Secure



Maintenance



4X / Year



Reference



Instruction Manual
L04-0447A



Owner's Manual E-Switch System
L04-0447C

Contact us



THAILAND OFFICE

+ (66 38) 468 008 ext 2001
info@maxliner.com
 700/135 Moo 5, Amata Nakorn,
 Klongtumru, Muang Chonburi, 20000 Thailand

EUROPE OFFICE

+ 31 (0) 850 201 887
infoEurope@vandapac.com
 Aphroditestraat 1, 5074TW Tilburg, Netherlands
 Chamber of Commerce : 71512799
 VAT identification number : NL858744272801

AUSTRALIA/OCEANIA OFFICE

+ 61 1800 592 192
sales@maxliner.com.au
 2 Dexter Drive Epping 3076 Australia




MAXLINER

INSTALLATION INSTRUCTIONS MANUAL

MAXTOP VENTURE

TOYOTA HILUX DOUBLE CAB 2018+ A-DECK



Contact us



THAILAND OFFICE

☎ + (66 38) 468 008 ext 2001
✉ info@maxliner.com
🏠 700/135 Moo 5, Amata Nakorn,
Klongtumru, Muang Chonburi, 20000 Thailand







EUROPE OFFICE

☎ + 31 (0) 850 201 887
✉ infoEurope@vandapac.com
🏠 Aphroditestraat 1, 5074TW Tilburg, Netherlands
Chamber of Commerce : 71512799
VAT identification number : NL858744272801











AUSTRALIA/OCEANIA OFFICE

☎ + 61 1800 592 192
✉ sales@maxliner.com.au
🏠 2 Dexter Drive Epping 3076 Australia

Component parts

A  1x	B  1x		
C  4x	D  20x	E  2x	F  1x
G  1x	H  6x	I  AAA / 4x	J  1x

Tools used

 No.10,12,14				
 No.T20		 No.4,5		
 Silicone (Non supply)				





Caution for installation

Read this mounting manual carefully, before your start the installation.


1. Area where to install product should be clean.
2. During installation, person who installed should take off any ornaments.
3. Wear the protective eyewear before installation.

Instruction procedure


1 LH/RH





1.1




1.2




2 LH/RH



2.1 (2x)




2.2 (4x)




Instruction procedure



3




4




5 LH/RH



5.1





5.2




Instruction procedure


6 LH/RH




6.1




6.2



6.3




7




8

8.1





8.2

8.3




Instruction procedure


9





9.1




9.2




10 LH/RH




10.1 (4x)



10.2 (2x)



11




Instruction procedure


12 LH/RH



12.1
(4x)




12.2
(2x)




12.1

12.2


12.1





13



13.1




13.2




14


14.1



14.2




14.3





Instruction procedure

15


15.1




15.2




15.3




15.4






15.5



15.6






16 LH/RH





Instruction procedure



17 LH/RH





18



**BEWARE OF
CRUSHING HAND**





19 LH/RH






Instruction procedure



20 LH/RH



21




22 LH/RH




Instruction procedure

23 LH/RH

23.1




23.2




24

24.1




24.2




25 LH/RH


25.1





25.2



25.3





25.4





Instruction procedure


26 LH/RH




27 LH/RH



28 LH/RH





① → ⑥





Instruction procedure


29 LH/RH




30 LH/RH




30.1




30.2




30.3







31.1




31.2




31.3




31.4







31.5









32.1




32.2







33.1




33.2




33.3




33.4




33.5




33.6




34





34.1




34.2



35






36.1




36.2




36.3




37




37.1




37.2




38



38.1




38.2




39


39.1




39.2




39.3




39.4



39.5




39.6




Instruction procedure


40




40.1




40.2




40.3




41




41.1





41.2





41.3



42





43




Instruction procedure


44




44.1




44.2




44.3




45




45.1





45.2






45.3




45.4






45.5




45.6






45.7




46



46.1




46.2




Instruction procedure



47




47.2





47.1




47.3





47.4



47.5




48




49

49.1




49.2





50


50.1





50.2




50.3



50.4




50.5




51

51.1




51.2





Instruction procedure

52

52.1



52.2



50 mm


57 mm

60 mm


A-A

B-B



C-C






53






54



55




56




※ Adjustment



※ Latch & Striker rear




1 LH/RH



(20x)





2 LH/RH





※ Latch & Striker rear

1.1



CASE 1 LH/RH




CASE 2 LH/RH




CASE 3 LH/RH





1.2



1.3





※ Latch & Striker side lift up





1.1

CASE 1 LH/RH





CASE 2 LH/RH




※ Latch & Striker side lift up

CASE 3 LH/RH





※ Latch & Striker side slide in lift up





1.1

CASE 1 LH/RH





CASE 2 LH/RH




※ Latch & Striker side slide in lift up


CASE 3 LH/RH





1.2



1.3



※ Sling rear




※ Sling rear



1.1




1x-3x




1.2





1.3




1.4




1.5




※ Side rod




1.1




1.2




1.3



1.4





1.5




※ Side rod

1.6




2 LH/RH


4




3 LH/RH





(20x)






4





※ Release inside





※ Front window guidelines





※ Front window guidelines




or



LOW



1st



2nd

